

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	2/21/2012	<b>Time:</b>	8:43 AM
<b>Name of School Corporation:</b>	SOUTH MONTGOMERY COMM SCH CORP			<b>Corp ID:</b>	545845
<b>Address of School Corporation:</b>	400 N Third St				
<b>City:</b>	New Market	<b>Zip:</b>	47965	<b>County Number:</b>	54
<b>VIN:</b>	4UZAAXCS34CL83634	<b>License Number:</b>	B787C	<b>Bus Number:</b>	6
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2004	<b>Make of Chassis:</b>	Freightliner
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown	<b>Year:</b>	2004
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Joel Flores	<b>PE:</b>	7415

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
36-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted).

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
36-2-1	Exhaust leak occurs in the exhaust system prior to the muffler outlet.
14-2-6	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely.

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.