

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|-------------------------------|-----------------|------------|------------------|-----------------------|
| Type of Inspection: | Annual | Date: | 4/18/2012 | Time: | 9:30 AM |
| Name of School Corporation: | HAMILTON SOUTHEASTERN SCHOOLS | | | Corp ID: | 293005 |
| Address of School Corporation: | 13485 Cumberland Rd | | | | |
| City: | Fishers | Zip: | 46038 | County Number: | 29 |
| VIN: | 1BABKBKA07F241644 | License Number: | | | 30334 |
| Make of Body: | Blue Bird Corporation | Year: | 2007 | Make of Chassis: | Blue Bird Corporation |
| Bus Type: | D | Mileage: | | | Unknown |
| Inspection Status: | O | Inspected By: | Chris Kath | | |
| | | PE: | 6690 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 34-1-4 | There is a significant fluid leak from the transmission. |
| 21-1-1 | Any clearance light is missing, cracked, faded, wrong color, or inoperative. |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 34-2-2 | There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire. |

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.