

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	5/18/2012	<b>Time:</b>	10:45 AM
<b>Name of School Corporation:</b>	SOUTH NEWTON SCHOOL CORP.			<b>Corp ID:</b>	565995
<b>Address of School Corporation:</b>	13232 S 50 E				
<b>City:</b>	Kentland	<b>Zip:</b>	47951	<b>County Number:</b>	56
<b>VIN:</b>	1GB6G2AG1A1134335	<b>License Number:</b>	83266	<b>Bus Number:</b>	5M
<b>Make of Body:</b>	Chevrolet	<b>Year:</b>	2010	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2010	<b>Mileage:</b>	Unknown	<b>Year:</b>	2010
<b>Bus Type:</b>		<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Nathan Sherer	<b>PE:</b>	7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
81-2-5	There is movement in a spring loaded drag link greater than 1/8 inch

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------