

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 7/11/2012	<b>Time:</b> 10:42 AM
<b>Name of School Corporation:</b>	NORTHERN WELLS COMM. SCHOOLS	<b>Corp ID:</b> 908435
<b>Address of School Corporation:</b>		
<b>City:</b>	<b>Zip:</b>	<b>County Number:</b> 90
<b>VIN:</b> 1GDHGG31F6Y1127758	<b>License Number:</b> 83246	<b>Bus Number:</b> 39
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2000	<b>Make of Chassis:</b> GMC
<b>Year:</b> 2000	<b>Mileage:</b> Unknown	
<b>Bus Type:</b>		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Brian Bills	<b>PE:</b> 5506

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
83-2-1	Any part of the step-well or support structure is rusted through

Bus Type Description