

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                            |                        |             |                         |              |
|---------------------------------------|----------------------------|------------------------|-------------|-------------------------|--------------|
| <b>Type of Inspection:</b>            | Post-Crash Inspection      | <b>Date:</b>           | 10/10/2012  | <b>Time:</b>            | 12:57 PM     |
| <b>Name of School Corporation:</b>    | SOUTHWEST SULLIVAN SCHOOLS | <b>Corp ID:</b>        | 777715      |                         |              |
| <b>Address of School Corporation:</b> | 110 N Main St              |                        |             |                         |              |
| <b>City:</b>                          | Sullivan                   | <b>Zip:</b>            | 47882       | <b>County Number:</b>   | 77           |
| <b>VIN:</b>                           | 4UZABRDD38CZ10876          | <b>License Number:</b> | B390F       | <b>Bus Number:</b>      | 11           |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.   | <b>Year:</b>           | 2008        | <b>Make of Chassis:</b> | Freightliner |
| <b>Bus Type:</b>                      | C                          | <b>Mileage:</b>        | Unknown     |                         |              |
| <b>Inspection Status:</b>             | O                          | <b>Inspected By:</b>   | Chuck Tharp | <b>PE:</b>              | 5618         |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                               |
|------------------------|--|
| 52-1-1                 | Any headlight is inoperative.                    |
| 93-1-4                 | Any front turn signal does not function properly |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 38-2-1                 | Mountings are broken or bent badly enough to inhibit proper adjustment.                                |
| 37-2-1                 | There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.). |
| 18-2-1                 | The front or rear bumper is missing, torn, loose or altered from original specifications.              |

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**