

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	1/31/2013	<b>Time:</b>	12:31 PM
<b>Name of School Corporation:</b>	SOUTH GIBSON SCHOOL CORP.	<b>Corp ID:</b>	262765		
<b>Address of School Corporation:</b>	1029 W 650 S				
<b>City:</b>	Fort Branch	<b>Zip:</b>	47648	<b>County Number:</b>	26
<b>VIN:</b>	4UZ6CJAA4XCB74692	<b>License Number:</b>	B563D	<b>Bus Number:</b>	1
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	1999	<b>Make of Chassis:</b>	Freightliner
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Chuck Sharp	<b>PE:</b>	5618

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
27-1-2	The first aid kit is not properly filled.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
22-2-1	Exhaust leak occurs in the exhaust system exceeding 1" measurable in any direction or 1/2" in diameter.
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking.
58-2-4	Stop arm does not function properly

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.