

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/4/2013	<b>Time:</b> 10:34 AM
<b>Name of School Corporation:</b> SOUTH RIPLEY COMM. SCHOOL CORP	<b>Corp ID:</b> 696865	
<b>Address of School Corporation:</b> PO Box 690		
<b>City:</b> Versailles	<b>Zip:</b> 47042	<b>County Number:</b> 69
<b>VIN:</b> 1GBHG31F1Y1123609	<b>License Number:</b> 6413	<b>Bus Number:</b> A4
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2000	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2000	<b>Mileage:</b> Unknown	<b>Year:</b> 2000
<b>Bus Type:</b>		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Chris Clark	<b>PE:</b> 6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Heater motor is not operating properly.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
54-2-7	There are any cracks in any steering component.

### Bus Type Description