

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|------------|-------------------------|--------------------------|
| Type of Inspection: | Annual | Date: | 5/1/2013 | Time: | 10:15 AM |
| Name of School Corporation: | RICHLAND-BEAN BLOSSOM C.S.CORP | | | Corp ID: | 535705 |
| Address of School Corporation: | 600 S Edgewood Dr | | | | |
| City: | Ellettsville | Zip: | 47429 | County Number: | 53 |
| VIN: | 1GDHG31R221213666 | License Number: | 63721 | Bus Number: | 51 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2002 | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type: | | Mileage: | Unknown | Year: | 2002 |
| Inspection Status: | R | Inspected By: | Mark Raper | PE: | 6473 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 61-1-2 | One (1) taillight or one (1) brake light does not function |
| 22-1-3 | An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |

Violations - Out of Service

Inspection Code Description

Bus Type Description