

## REPORT OF SCHOOL BUS INSPECTION

|  |                                   |  |
|--|-----------------------------------|--|
| <b>Type of Inspection:</b> Annual                            | <b>Date:</b> 6/11/2013            | <b>Time:</b> 9:46 AM                   |
| <b>Name of School Corporation:</b> NORTHWESTERN SCHOOL CORP. | <b>Corp ID:</b> 343470            |  |
| <b>Address of School Corporation:</b> 3075 N Washington St   |                                   |  |
| <b>City:</b> Kokomo  | <b>Zip:</b> 46901                 | <b>County Number:</b> 34               |
| <b>VIN:</b> 4DRBRAAN13A954023                                | <b>License Number:</b> B429D      | <b>Bus Number:</b> 10                  |
| <b>Make of Body:</b> IC Corporation                          | <b>Year:</b> 2003                 | <b>Make of Chassis:</b> IC Corporation |
| <b>Year:</b> 2003  | <b>Mileage:</b> Unknown           | <b>Year:</b> 2003                      |
| <b>Bus Type:</b> C   |                                   |  |
| <b>Inspection Status:</b> O                                  | <b>Inspected By:</b> Randy McPike | <b>PE:</b> 7018                        |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 2-1-1                  | Required back-up lights do not function.   |
| 45-1-2                 | Seat back or bottom is loose.  |
| 52-1-3                 | Spring hanger bushings or torque leaf bushings are worn, loose, broken or missing  |
| 22-1-3                 | An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 58-2-3                 | Stop arm does not fully extend to a right angle to the bus |

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**