

REPORT OF SCHOOL BUS INSPECTION

| | | |
|---|---------------------------------|---|
| Type of Inspection: Post-Crash Inspection | Date: 9/26/2013 | Time: 9:24 AM |
| Name of School Corporation: MOORESVILLE CONS. SCHOOL CORP. | Corp ID: 555930 | |
| Address of School Corporation: 173 Indianapolis Rd | | |
| City: Mooresville | Zip: 46158 | County Number: 55 |
| VIN: 1BABKCKH47F239463 | License Number: 30308 | Bus Number: 46 |
| Make of Body: Blue Bird Corporation | Year: 2007 | Make of Chassis: Blue Bird Corporation |
| Year: 2007 | Year: 2007 | |
| Bus Type: D | Mileage: Unknown | |
| Inspection Status: O | Inspected By: Mark Raper | PE: 6473 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 56-1-2 | Step-well area is weakened |
| 23-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails. |
| 63-1-4 | Front turn signal does not function properly |
| 63-1-2 | A lens is cracked, missing or wrong color |
| 67-1-1 | Washers do not function properly in any manner |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 69-2-1 | Glass or glazing is broken through or missing |
| 56-2-1 | Part of the step-well or support structure is rusted through |
| 23-2-1 | There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.). |
| 54-2-3 | Any steering component jams or inhibits safe movement |

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.