

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	10/8/2013	<b>Time:</b>	10:36 AM
<b>Name of School Corporation:</b>	SPRINGS VALLEY COMM. SCH. CORP	<b>Corp ID:</b>	596160		
<b>Address of School Corporation:</b>	498 S Larry Bird Blvd				
<b>City:</b>	French Lick	<b>Zip:</b>	47432	<b>County Number:</b>	59
<b>VIN:</b>	1FDSE35F2YHB23946	<b>License Number:</b>	36673	<b>Bus Number:</b>	1A
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2000	<b>Make of Chassis:</b>	Ford
<b>Bus Type:</b>		<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Kelly Hammond	<b>PE:</b>	6682

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.
54-1-2	There is movement at any spring loaded drag link or the rod end (using hand pressure).

### Violations - Out of Service

Inspection Code Description

Bus Type Description