

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	12/3/2013	Time:	9:00 AM
Name of School Corporation:	WASHINGTON COMM. SCHOOLS, INC.			Corp ID:	141405
Address of School Corporation:	301 E South St			County Number:	
City:	Washington	Zip:	47501	County Number:	14
VIN:	1T7HT4B211104754	License Number:	6059	Bus Number:	1
Make of Body:	Thomas Built Buses, Inc.	Year:	2001	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	Unknown
Inspection Status:	O	Inspected By:	Travis Coryea	PE:	5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-3	An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
21-1-1	A dripping oil or fluid leak.
49-1-1	The seat belt cutter is not located within the drivers reach.
73-1-1	The anti-vandalism device fails to operate.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
69-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
22-2-1	Exhaust leak occurs in the exhaust system exceeding 1" measurable in any direction or 1/2" in diameter.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.