

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	12/4/2013	<b>Time:</b>	8:55 AM
<b>Name of School Corporation:</b>	HUNTINGTON CO. COMM. SCH. CORP	<b>Corp ID:</b>	353625		
<b>Address of School Corporation:</b>	1360 N Warren Rd				
<b>City:</b>	Huntington	<b>Zip:</b>	46750	<b>County Number:</b>	35
<b>VIN:</b>	4UZABRDJ19CAB0340	<b>License Number:</b>	32382	<b>Bus Number:</b>	28
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2008	<b>Make of Chassis:</b>	Freightliner
<b>Year:</b>	2008	<b>Mileage:</b>	Unknown	<b>PE:</b>	6458
<b>Bus Type:</b>	C	<b>Inspected By:</b>	Jamie Hotchkiss	<b>PE:</b>	6458
<b>Inspection Status:</b>	O				

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
17-1-2	The drive shaft has excessive up and down, or side to side movement at any universal joint or carrier bearing.
11-1-1	The front bumper does not extend to the edge of the fenders.
35-1-2	The latch is not properly aligned, loose or badly rusted.
32-1-2	The grill is missing.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
30-2-1	Frame is deteriorated, cracked, broken or severely bent.
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
21-2-2	There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire.

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.