

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 7/14/2014	<b>Time:</b> 2:45 PM
<b>Name of School Corporation:</b> NORTHERN WELLS COMM. SCHOOLS	<b>Corp ID:</b> 908435	
<b>Address of School Corporation:</b>		
<b>City:</b>	<b>Zip:</b>	<b>County Number:</b> 90
<b>VIN:</b> 1FDXE4TPX6DB25548	<b>License Number:</b> 72235	<b>Bus Number:</b> 33
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2006	<b>Make of Chassis:</b> Ford
<b>Year:</b> 2006	<b>Mileage:</b> Unknown	
<b>Bus Type:</b>		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Jamie Hotchkiss	<b>PE:</b> 6458

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
110-1-1	The lifting mechanism is unable to lift a minimum load of 800 pounds

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------