

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	7/16/2014	<b>Time:</b>	9:26 AM		
<b>Name of School Corporation:</b>	NORTHERN WELLS COMM. SCHOOLS			<b>Corp ID:</b>	908435		
<b>Address of School Corporation:</b>							
<b>City:</b>		<b>Zip:</b>		<b>County Number:</b>	90		
<b>VIN:</b>	1FDXE4TPX6DB25548	<b>License Number:</b>	72235	<b>Bus Number:</b>	33		
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2006	<b>Make of Chassis:</b>	Ford	<b>Year:</b>	2006
<b>Bus Type:</b>			<b>Mileage:</b>	Unknown			
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Jamie Hotchkiss	<b>PE:</b>	6458		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
110-1-1	The lifting mechanism is unable to lift a minimum load of 800 pounds

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------