REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:AnnualDate:7/30/2014Time:11:17 AM

Name of School Corporation: SETON CATHOLIC SCHOOL Corp ID: D842

Address of School Corporation: 233 South 5th Street

City:RichmondZip:47374County Number:89VIN:1HVBRABN91A937335License Number:b362jBus Number:4Make of Body:AmTranYear:2001Make of Chassis:IC CorporationYear:2001

Bus Type: C Mileage: Unknown

Inspection Status: O Inspected By: Jeremy Mason PE: 8139

Violations - Rejected

| Inspection Code | <u>Description</u> |
|--------------------|--|
| 22-1-2 | Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted). |
| 22-1-3 | An exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |
| 63-1-4 | Front turn signal does not function properly |

Violations - Out of Service

| <u>Inspection</u> <u>Code</u> | <u>Description</u> |
|----------------------------------|---|
| 22-2-1 | Exhaust leak occurs in the exhaust system exceeding 1" measurable in any direction or 1/2" in diameter. |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.