

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	8/5/2014	<b>Time:</b>	9:33 AM
<b>Name of School Corporation:</b>	MACONAQUAH SCHOOL CORPORATION	<b>Corp ID:</b>	525615		
<b>Address of School Corporation:</b>	7932 S Strawtown Pike				
<b>City:</b>	Bunker Hill	<b>Zip:</b>	46914	<b>County Number:</b>	52
<b>VIN:</b>	4UZABRDT8GCHF8579	<b>License Number:</b>	36		
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2016	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
33-1-1	Headlight is inoperative.
63-1-4	Front turn signal does not function properly
69-1-2	There are intersecting cracks in the windshield area covered by the wipers
69-1-4	There is cracked glass to the immediate right or left of the driver

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking.
58-2-4	Stop arm does not function properly
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**