

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	8/6/2014	<b>Time:</b>	10:30 AM
<b>Name of School Corporation:</b>	EVANSVILE MATER DEI	<b>Corp ID:</b>	82MaterDei		
<b>Address of School Corporation:</b>	1300 Harmony Way				
<b>City:</b>	Evansville	<b>Zip:</b>	47720	<b>County Number:</b>	82
<b>VIN:</b>	1GBJG31U561238758	<b>License Number:</b>	B334AC	<b>Bus Number:</b>	1
<b>Make of Body:</b>	Chevrolet	<b>Year:</b>	2006	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2006	<b>Year:</b>	2006		
<b>Bus Type:</b>		<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Bradley Miller	<b>PE:</b>	7809

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
22-2-1	Exhaust leak occurs in the exhaust system exceeding 1" measurable in any direction or 1/2" in diameter.

Bus Type Description