

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	9/18/2014	<b>Time:</b>	2:57 PM
<b>Name of School Corporation:</b>	ZIONSVILLE COMMUNITY SCHOOLS			<b>Corp ID:</b>	60630
<b>Address of School Corporation:</b>	9770 E CR 600S				
<b>City:</b>	Zionsville	<b>Zip:</b>	46077	<b>County Number:</b>	6
<b>VIN:</b>	1BABKCPA03F207096	<b>License Number:</b>	18922	<b>Bus Number:</b>	50
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2003	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	D	<b>Mileage:</b>	Unknown	<b>Year:</b>	2003
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Edwin Davis	<b>PE:</b>	3981

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-4	Front turn signal does not function properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).
11-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
50-2-1	The service door does not open or close properly
56-2-1	Part of the step-well or support structure is rusted through

### Bus Type Description

**Type D School Bus** – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.