

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	4/9/2015	<b>Time:</b>	10:37 AM
<b>Name of School Corporation:</b>	RANDOLPH SOUTHERN SCHOOL CORP.			<b>Corp ID:</b>	686805
<b>Address of School Corporation:</b>	One Rebel Dr				
<b>City:</b>	Lynn	<b>Zip:</b>	47355	<b>County Number:</b>	68
<b>VIN:</b>	1BAKF2PHX9F266814	<b>License Number:</b>	13169	<b>Bus Number:</b>	6
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2008	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Year:</b>	2009	<b>Mileage:</b>	44837	<b>PE:</b>	6458
<b>Bus Type:</b>	C	<b>Inspected By:</b>	Jamie Hotchkiss		
<b>Inspection Status:</b>	O				

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-4	Stop arm does not function properly
59-2-3	Stop arm does not fully extend to a right angle to the bus

#### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.