

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/18/2015	<b>Time:</b>	10:08 AM
<b>Name of School Corporation:</b>	RENSELAER CENTRAL SCHOOL CORP			<b>Corp ID:</b>	373815
<b>Address of School Corporation:</b>	900 E Washington				
<b>City:</b>	Rensselaer	<b>Zip:</b>	47978	<b>County Number:</b>	37
<b>VIN:</b>	1GBJG316X91164744	<b>License Number:</b>	MO76930	<b>Bus Number:</b>	09
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2009	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	2009
<b>Bus Type:</b>		<b>Mileage:</b>	135810		
<b>Inspection Status:</b>	<input type="radio"/>	<b>Inspected By:</b>	Nathan Sherer	<b>PE:</b>	7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
64-2-2	LED type lights have 50% or more of the pixels inoperable in any one rear light
50-2-1	There is no seat belt cutter in the vehicle

### Bus Type Description