

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	11/5/2015	<b>Time:</b>	7:48 AM
<b>Name of School Corporation:</b>	NORTH NEWTON SCHOOL CORP.			<b>Corp ID:</b>	565945
<b>Address of School Corporation:</b>	PO Box 8				
<b>City:</b>	Morocco	<b>Zip:</b>	47963	<b>County Number:</b>	56
<b>VIN:</b>	4DRAPSKK9CB389719	<b>License Number:</b>	84445	<b>Bus Number:</b>	32
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2012	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	B	<b>Mileage:</b>	105564	<b>Year:</b>	2012
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Nathan Sherer	<b>PE:</b>	7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly
53-2-5	'U' bolts are loose, broken, or missing

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**