

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Post-Crash Inspection	<b>Date:</b> 3/16/2016	<b>Time:</b> 9:04 AM
<b>Name of School Corporation:</b> SCHOOL TOWN OF MUNSTER	<b>Corp ID:</b> 454740	
<b>Address of School Corporation:</b> 8616 Columbia Ave		
<b>City:</b> Munster	<b>Zip:</b> 46321	<b>County Number:</b> 45
<b>VIN:</b> 4DRBWAAN69A042327	<b>License Number:</b> 32437	<b>Bus Number:</b> 35
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2009	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2009	<b>Mileage:</b> 63079	<b>Year:</b> 2009
<b>Bus Type:</b> D		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Dale Morgan	<b>PE:</b> 4743

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-2	Step-well area is weakened
34-1-1	Any headlight is inoperative
64-1-4	Any front turn signal does not function properly
59-1-7	Any optional rear stop arm device or school bus crossing arm criteria is not met
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
51-2-1	The service door does not open or close properly

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.