

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	6/7/2016	<b>Time:</b>	11:07 AM
<b>Name of School Corporation:</b>	SOUTHEAST FOUNTAIN SCHOOL CORP			<b>Corp ID:</b>	232455
<b>Address of School Corporation:</b>	744 E US 136				
<b>City:</b>	Veedersburg	<b>Zip:</b>	47987	<b>County Number:</b>	23
<b>VIN:</b>	1GBHG31U661221482	<b>License Number:</b>	10203	<b>Bus Number:</b>	33
<b>Make of Body:</b>	Chevrolet	<b>Year:</b>	2007	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2007	<b>Year:</b>	2007		
<b>Bus Type:</b>		<b>Mileage:</b>	86872		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Nate King	<b>PE:</b>	7421

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-1	Any crossmember is cracked or broken
14-2-2	Any crossmember is rusted sufficiently to weaken floor supports

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------