

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/1/2017	<b>Time:</b> 1:43 PM
<b>Name of School Corporation:</b> SOUTHEAST FOUNTAIN SCHOOL CORP	<b>Corp ID:</b> 232455	
<b>Address of School Corporation:</b> 744 E US 136		
<b>City:</b> Veedersburg	<b>Zip:</b> 47987	<b>County Number:</b> 23
<b>VIN:</b> 1GDJG31K091156706	<b>License Number:</b> 80979	<b>Bus Number:</b> 34
<b>Make of Body:</b> Carpenter	<b>Year:</b> 2010	<b>Make of Chassis:</b> GMC
<b>Bus Type:</b>	<b>Mileage:</b> 102036	<b>Year:</b> 2010
<b>Inspection Status:</b> O	<b>Inspected By:</b> Nate King	<b>PE:</b> 7421

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-2	Any crossmember is rusted sufficiently to weaken floor supports
14-2-1	Any crossmember is cracked or broken

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------