

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/23/2017	<b>Time:</b> 8:54 AM
<b>Name of School Corporation:</b> SOUTH HENRY SCHOOL CORPORATION	<b>Corp ID:</b> 333415	
<b>Address of School Corporation:</b> 6972 SR 103		
<b>City:</b> Straughn	<b>Zip:</b> 47397	<b>County Number:</b> 33
<b>VIN:</b> 1BAKGCPH29F262012	<b>License Number:</b> 32270	<b>Bus Number:</b> 18
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2009	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Bus Type:</b> B	<b>Mileage:</b> 96850	<b>Year:</b> 2008
<b>Inspection Status:</b> O	<b>Inspected By:</b> Jeremy Mason	<b>PE:</b> 8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (½) inch in diameter.
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

### Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.