

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	6/27/2017	<b>Time:</b>	8:55 AM
<b>Name of School Corporation:</b>	WASHINGTON COMM. SCHOOLS, INC.			<b>Corp ID:</b>	141405
<b>Address of School Corporation:</b>	301 E South St				
<b>City:</b>	Washington	<b>Zip:</b>	47501	<b>County Number:</b>	14
<b>VIN:</b>	1T7YN3B2241134290	<b>License Number:</b>	19249	<b>Bus Number:</b>	16
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2002	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	D	<b>Mileage:</b>	125751	<b>Year:</b>	2004
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Kelly Hammond	<b>PE:</b>	6682

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-2	One (1) taillight or one (1) brake light does not function
70-1-7	Any emergency window is too difficult to open
68-1-1	Washers do not function properly in any manner
57-1-5	Step-well light is missing or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
46-2-3	Flip seat does not stay in the upright position when no passengers are seated

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**