REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		Date:	1/29/2018	Time:	12:22 PM
Name of Schoo Address of Sch	I Corporation: MAG ool Corporation:	CONAQUAH S 7932 S Stra	SCHOOL CORPO owtown Pike	DRATION	Corp ID:	525615
City:	Bunker Hill	Zip:	46914		County Number:	52
VIN:	1T7YT4A2781290988		License Number:	30602	Bus Number:	38
Make of Body:	Thomas Built Buses, Yea Inc.	r : 2006	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2008
Bus Type:	D		Mileage:	116102		
Inspection Status:	0	Inspected By:	Randy McPike		PE:	7018

Violations - Rejected

Inspection Code	<u>Description</u>
90-1-4	A trash container is located rearmost seats of a rear engine bus or at the back of a wheel chair equipped bus
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
67-1-5	See Notes: Any defect inspector deems a violation not listed
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
46-1-2	Any seat back or bottom is loose
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection</u> <u>Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required
	after 5-2-94

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus,

behind the rear wheels, or midship between the wheels.	ne front and rear axles.	The entrance door is ahe	ead of the front