

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	2/1/2018	<b>Time:</b>	2:57 PM
<b>Name of School Corporation:</b>	SOUTH RIPLEY COMM. SCHOOL CORP	<b>Corp ID:</b>	696865		
<b>Address of School Corporation:</b>	PO Box 690				
<b>City:</b>	Versailles	<b>Zip:</b>	47042	<b>County Number:</b>	69
<b>VIN:</b>	4UZAAXCT84CL82925	<b>License Number:</b>	19558	<b>Bus Number:</b>	114
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2002	<b>Make of Chassis:</b>	Freightliner
<b>Bus Type:</b>	C	<b>Mileage:</b>	137185	<b>Year:</b>	2004
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Chris Clark	<b>PE:</b>	6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
51-1-4	See Notes: Any defect inspector deems a violation not listed
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
34-1-1	Any headlight is inoperative
58-1-1	Any stirrup step or handle is broken, loose or missing
58-1-2	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**