

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	11/27/2018	<b>Time:</b>	10:52 AM
<b>Name of School Corporation:</b>	SOUTH ADAMS SCHOOLS			<b>Corp ID:</b>	10035
<b>Address of School Corporation:</b>	1000 West Parkway				
<b>City:</b>	Berne	<b>Zip:</b>	46711	<b>County Number:</b>	1
<b>VIN:</b>	4DRBUSKN3BB340599	<b>License Number:</b>	75029	<b>Bus Number:</b>	17
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2010	<b>Make of Chassis:</b>	IC Corporation
		<b>Year:</b>		<b>Year:</b>	2011
<b>Bus Type:</b>	C	<b>Mileage:</b>	106021		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Jamie Hotchkiss	<b>PE:</b>	6458

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
82-1-2	See Notes: Any defect inspector deems a violation not listed
51-1-4	See Notes: Any defect inspector deems a violation not listed
41-1-2	Any interior protrusions have sharp edges or corners
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
31-2-1	Frame is deteriorated, cracked, broken or severely bent
51-2-1	The service door does not open or close properly
70-2-1	Any glass or glazing is broken through or missing

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.