

REPORT OF SCHOOL BUS INSPECTION

| | | |
|---|--------------------------------------|--|
| Type of Inspection: Semi-Annual | Date: 1/16/2020 | Time: 10:42 AM |
| Name of School Corporation: NORTHERN WELLS COMM. SCHOOLS | Corp ID: 908435 | |
| Address of School Corporation: | | |
| City: | Zip: | County Number: 90 |
| VIN: 4DRBUAAN85B974488 | License Number: 4216 | Bus Number: 14 |
| Make of Body: IC Corporation | Year: 2004 | Make of Chassis: IC Corporation |
| Year: 2005 | | |
| Bus Type: C | Mileage: 263158 | |
| Inspection Status: O | Inspected By: Jamie Hotchkiss | PE: 6458 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 57-1-5 | Step-well light is missing or inoperative |
| 52-1-2 | Any shock absorber is leaking fluid |
| 23-1-5 | Any hanger, clamp or bracket is missing, loose or broken |
| 23-1-2 | Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted) |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 22-2-2 | There is a significant leak from the engine or transmission onto the exhaust system which could potentially cause a fire |
| 70-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.