

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 7/13/2020	<b>Time:</b> 10:28 AM
<b>Name of School Corporation:</b> TRI-COUNTY SCHOOL CORPORATION	<b>Corp ID:</b> 918535	
<b>Address of School Corporation:</b>		
<b>City:</b>	<b>Zip:</b>	<b>County Number:</b> 91
<b>VIN:</b> 4UZABRFC5LCLV1747	<b>License Number:</b> 5	<b>Bus Number:</b> 8
<b>Make of Body:</b> Thomas Built Buses, Inc. <b>Year:</b> 2019	<b>Make of Chassis:</b> Freightliner	<b>Year:</b> 2020
<b>Bus Type:</b>	<b>Mileage:</b> 13400	
<b>Inspection Status:</b> R	<b>Inspected By:</b> Nate King	<b>PE:</b> 7421

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-2	Any shock absorber is leaking fluid

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------