REPORT OF SCHOOL BUS INSPECTION

Type of 9:16 Annual Date: 8/20/2020 **Time**: Inspection: AM SHERIDAN COMMUNITY SCHOOLS 293055 Name of School Corporation: Corp ID: **Address of School Corporation:** 24795 Hinsley Rd County City: Sheridan Zip: 46069 29 Number: License VIN: 1T7YR4E2XC1144005 7629 **Bus Number:** 10 Number: Make of Thomas Built Buses, **Year**: 2012 Make of Body: Freightliner Year: 2012 Inc. Chassis: **Bus Type:** D Mileage: 79155 Inspected PE: **Inspection Status:** O Joel Flores 7415 By:

Violations - Rejected

Inspection Code	<u>Description</u>
22-1-1	A dripping oil or fluid leak
20-1-2	Excessive effort is needed to open the emergency door
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
70-1-9	If the words "EMERGENCY EXIT" does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
11-1-7	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.