

REPORT OF SCHOOL BUS INSPECTION

| | | |
|--|---|-----------------------------------|
| Type of Inspection: Annual | Date: 9/24/2020 | Time: 9:05 AM |
| Name of School Corporation: SCECINA MEMORIAL SCHOOL | Corp ID: 49C710 | |
| Address of School Corporation: 5000 Nowland Ave | | |
| City: Indianapolis | Zip: 46201 | County Number: 49 |
| VIN: 1GBJ6310041152271 | License Number: B315AB | Bus Number: 2 |
| Make of Body: Chevrolet | Year: 2004 | Make of Chassis: Chevrolet |
| Bus Type: | Mileage: 55643 | Year: 2004 |
| Inspection Status: O | Inspected By: Jeff Kastenschmidt | PE: 5805 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 50-1-2 | The seat belt cutter is not secured using a positive fastening method. |
| 35-1-3 | See Notes: Any defect inspector deems a violation not listed |
| 70-1-1 | There is unapproved glazing material installed in the bus |
| 55-1-6 | See Notes: Any defect inspector deems a violation not listed |
| 41-1-2 | Any interior protrusions have sharp edges or corners |
| 24-1-7 | See Notes: Any defect inspector deems a violation not listed |
| 24-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |
| 46-1-5 | Upholstery or padding is ripped, torn, or improperly repaired |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 70-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |
| 24-2-1 | There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)). |

Bus Type Description