

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 12/4/2020 **Time:** 8:56 AM
Name of School Corporation: HONEY GROVE EDUCATIONAL DAYCARE **Corp ID:** 41001Z
Address of School Corporation: 1709 S SR 135
City: Greenwood **Zip:** 46143 **County Number:** 41
VIN: 1GBHG31RXX1146766 **License Number:** B958AB **Bus Number:** 2
Make of Body: Chevrolet **Year:** 1999 **Make of Chassis:** Chevrolet **Year:** 1999
Bus Type: **Mileage:** 128864
Inspection Status: O **Inspected By:** Joel Flores **PE:** 7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-6	See Notes: Any defect inspector deems a violation not listed
50-1-3	The seat belt cutter is contained in a compartment.
50-1-2	The seat belt cutter is not secured using a positive fastening method.
49-1-3	The reflective material is not National School Bus Yellow or white if on an MFSAB, or Black if on a bumper.
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description