

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 12/4/2020      **Time:** 8:56 AM  
**Name of School Corporation:** HONEY GROVE EDUCATIONAL DAYCARE      **Corp ID:** 41001Z  
**Address of School Corporation:** 1709 S SR 135  
**City:** Greenwood      **Zip:** 46143      **County Number:** 41  
**VIN:** 1GBHG31RXX1146766      **License Number:** B958AB      **Bus Number:** 2  
**Make of Body:** Chevrolet      **Year:** 1999      **Make of Chassis:** Chevrolet      **Year:** 1999  
**Bus Type:**      **Mileage:** 128864  
**Inspection Status:** O      **Inspected By:** Joel Flores      **PE:** 7415

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 28-1-6                 | See Notes: Any defect inspector deems a violation not listed   |
| 50-1-3                 | The seat belt cutter is contained in a compartment.  |
| 50-1-2                 | The seat belt cutter is not secured using a positive fastening method.   |
| 49-1-3                 | The reflective material is not National School Bus Yellow or white if on an MFSAB, or Black if on a bumper.  |
| 41-1-8                 | The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device. |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 8-2-1                  | There is no brake certification, or the certification has expired or is not signed |

### Bus Type Description