

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	3/25/2021	<b>Time:</b>	10:06 AM
<b>Name of School Corporation:</b>	LINTON-STOCKTON SCH CORP	<b>Corp ID:</b>	282950		
<b>Address of School Corporation:</b>	801 Northeast First St				
<b>City:</b>	Linton	<b>Zip:</b>	47441	<b>County Number:</b>	28
<b>VIN:</b>	1GDJG31K781161996	<b>License Number:</b>	77709	<b>Bus Number:</b>	SP4
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2008	<b>Make of Chassis:</b>	GMC
<b>Year:</b>	2008	<b>Year:</b>	2008	<b>Year:</b>	2008
<b>Bus Type:</b>		<b>Mileage:</b>	68224		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Mark Raper	<b>PE:</b>	6473

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body

### Violations - Out of Service

Inspection Code Description

### Bus Type Description