

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|--------------------------------|-----------------------|---------------|--------------------|------------------|-----------------------|-------|------|
| Type of Inspection: | Annual | Date: | 4/14/2021 | Time: | 10:51 AM | | |
| Name of School Corporation: | CARMEL CLAY SCHOOLS | | | Corp ID: | 293060 | | |
| Address of School Corporation: | 5185 E 131st St | | | | | | |
| City: | Carmel | Zip: | 46032 | County Number: | 29 | | |
| VIN: | 1BABNBPA6GF318890 | | License Number: | 10187 | Bus Number: | 62 | |
| Make of Body: | Blue Bird Corporation | Year: | 2015 | Make of Chassis: | Blue Bird Corporation | Year: | 2016 |
| Bus Type: | D | | | Mileage: | 40818 | | |
| Inspection Status: | R | Inspected By: | Jeff Kastenschmidt | PE: | 5805 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 55-1-6 | See Notes: Any defect inspector deems a violation not listed |
| 22-1-1 | A dripping oil or fluid leak |
| 70-1-9 | If the words "EMERGENCY EXIT" does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus |
| 70-1-10 | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.