REPORT OF SCHOOL BUS INSPECTION

Type of 9:19 Annual 4/27/2021 **Time**: Date: Inspection: AM Name of School Corporation: OAK HILL UNITED SCHOOL CORP. Corp ID: 525625 PO Box 550 **Address of School Corporation:** County City: Converse Zip: 46919 52 Number: License VIN: 4UZABRDT2FCFW5637 1115 Bus Number: Number: Make of Thomas Built Buses, **Year**: 2013 Freightliner Year: Make of Body: 2015 Inc. Chassis: **Bus Type:** С Mileage: 66596 Inspected PE: 7018 **Inspection Status:** R Randy McPike By:

Violations - Rejected

Inspection Code	<u>Description</u>
35-1-1	A heater motor is not operating properly
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
52-1-2	Any shock absorber is leaking fluid

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.