

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	8/13/2021	<b>Time:</b>	10:05 AM
<b>Name of School Corporation:</b>	SPENCER-OWEN COMMUNITY SCHOOLS			<b>Corp ID:</b>	606195
<b>Address of School Corporation:</b>	205 E Hillside				
<b>City:</b>	Spencer	<b>Zip:</b>	47460	<b>County Number:</b>	60
<b>VIN:</b>	4DRBUAAN1FB029397	<b>License Number:</b>	10050	<b>Bus Number:</b>	1
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2013	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	84000	<b>Year:</b>	2015
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Mark Raper	<b>PE:</b>	6473

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-2	Step-well area is weakened
33-1-2	The grill is missing
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
53-2-1	Any broken main leaf in a leaf spring
31-2-1	Frame is deteriorated, cracked, broken or severely bent
51-2-1	The service door does not open or close properly
48-2-2	There is a severe leak from any point
26-2-1	The fire extinguisher is missing
3-2-2	Wiring is exposed.
36-2-1	The latch mechanism is missing
22-2-1	There are missing or broken motor mounts
18-2-1	Yokes: any visible crack in a yoke end, any yoke mounting hardware loose, horizontal or vertical movement of slip joint yoke great than half (1/2) inch, any loose, broken or missing end fitting fastener
63-2-3	Any tire is flat
34-2-1	Both lamps are inoperative on low beam
70-2-1	Any glass or glazing is broken through or missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### **Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**