REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			Date:	1/5/2022	Time:	8:59 AM
		CRO	OWN POINT COMM. SCHOOL CORP.			Corp ID:	454660
Address of School Corporation:			1151 E Summit				
City:	Crown Point		Zip:	46307		County Number:	45
VIN:	4UZABRDT7HCHW83	50		License Number:	19903	Bus Number:	14
Make of Body:	Thomas Built Buses, Inc.	Year:	: 2016	Make of Chassis:	Freightliner	Year:	2017
Bus Type:	С			Mileage:	41448		
Inspection Status: O		Inspected By:	Nathan Sherer		PE:	7029	

Violations - Rejected

Inspection Code	Description				
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.				
55-1-6	See Notes: Any defect inspector deems a violation not listed				
82-1-2	See Notes: Any defect inspector deems a violation not listed				
48-1-1	Power steering unit leaks at any point				

Violations - Out of Service

<u>Inspection</u> <u>Code</u>	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.