

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	1/25/2022	<b>Time:</b>	1:42 PM
<b>Name of School Corporation:</b>	TRI-CENTRAL SCHOOLS	<b>Corp ID:</b>	807935		
<b>Address of School Corporation:</b>	2115 W 500 N				
<b>City:</b>	Sharpsville	<b>Zip:</b>	46068	<b>County Number:</b>	80
<b>VIN:</b>	1BAKF2CPH68F250477	<b>License Number:</b>	B709Q	<b>Bus Number:</b>	2
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2007	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	137623	<b>Year:</b>	2008
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
51-1-4	See Notes: Any defect inspector deems a violation not listed
57-1-8	See Notes: Any defect inspector deems a violation not listed
57-1-5	Step-well light is missing or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
51-2-1	The service door does not open or close properly

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**