REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | Date: | 4/12/2022 | Time: | 9:48 AM |
|---|-----------------|---------------|------------------|-----------|-----------------------|---------|
| Name of School Corporation: GRIFFITH PUBLIC SCHOOLS | | | | | Corp ID: | 454700 |
| Address of School | Corporation: | 602 N Raymon | d | | | |
| City: | Griffith | Zip: | 46319 | | County Number: | 45 |
| VIN: | 1GB3G3BG4D | 1183766 | License Number: | 59900 | Bus Number: | 25 |
| Make of Body: | Starcraft Year: | 2013 | Make of Chassis: | Chevrolet | Year: | 2013 |
| Bus Type: | | | Mileage: | 97513 | | |
| Inspection Status: | 0 | Inspected By: | Nathan Sherer | | PE: | 7029 |

Violations - Rejected

| Inspection <u>Code</u> | Description |
|---------------------------|--|
| 57-1-5 | Step-well light is missing or inoperative |
| 28-1-4 | The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction. |
| 23-1-2 | Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted) |

Violations - Out of Service

| Inspection Code | Description |
|-----------------|---|
| 50-2-1 | There is no seat belt cutter in the vehicle |

Bus Type Description