REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Semi-Annual | | | Date: | 10/4/2022 | Time: | 10:35 AM |
|--------------------------------|-----------------------------|-------|------------------------------|--------------------|--------------|-------------------|-------------|
| | | MAN | MANCHESTER COMMUNITY SCHOOLS | | Corp ID: | 858045 | |
| Address of School Corporation: | | | PO Box 308 | | | | |
| City: | North Manchester | | Zip: | 46962 | | County Number: | 85 |
| VIN: | 4UZABRDU49CAH003 | 9 | | License Number: | 2212 | Bus Number: | 15 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2008 | Make of Chassis: | Freightliner | Year: | 2009 |
| Bus Type: | С | | | Mileage: | 191190 | | |
| Inspection Status: | 0 | | Inspected By: | Randy McPike | | PE: | 7018 |

Violations - Rejected

| Inspection Code | <u>Description</u> |
|--------------------|--|
| 20-1-8 | If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly |
| 90-1-3 | The trash container is not secured to prevent movement and does not allow for easy removal and replacement |
| 68-1-1 | Washers do not function properly in any manner |

Violations - Out of Service

| Inspection Code | <u>Description</u> |
|-----------------|--|
| 8-2-1 | There is no brake certification, or the certification has expired or is not signed |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.