

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	10/20/2022	<b>Time:</b>	10:28 AM
<b>Name of School Corporation:</b>			GRACE BAPTIST CHRISTIAN SCHOOL	<b>Corp ID:</b>	IN240873
<b>Address of School Corporation:</b> 1830 N Michigan St.					
<b>City:</b>	Plymouth	<b>Zip:</b>	46563	<b>County Number:</b>	50
<b>VIN:</b>	4UZAAXAK12CJ78698	<b>License Number:</b>	B534AB	<b>Bus Number:</b>	1
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2001	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	120000	<b>Year:</b>	2001
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Travis Harrold	<b>PE:</b>	8022

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
29-1-4	Prohibited area line is missing or improper
29-1-5	Prohibited area sign is missing or obscured

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
50-2-1	There is no seat belt cutter in the vehicle

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**