

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	10/20/2022	<b>Time:</b>	11:36 AM
<b>Name of School Corporation:</b>	ELKHART COMMUNITY SCHOOLS	<b>Corp ID:</b>	202305		
<b>Address of School Corporation:</b>	2720 California Rd				
<b>City:</b>	Elkhart	<b>Zip:</b>	46514	<b>County Number:</b>	20
<b>VIN:</b>	4DRBWTAR9MB443226	<b>License Number:</b>	24414	<b>Bus Number:</b>	102
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2020	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>			2021	<b>Year:</b>	2021
<b>Bus Type:</b>	D	<b>Mileage:</b>	2857		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Joseph Hartman	<b>PE:</b>	7257

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
68-1-3	Reservoir is empty

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**