REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Semi-Annual | | | Date: | 10/26/2022 | Time: | 8:51 AM |
|--------------------------------|-----------------------------|-------|--------------------------------|---------------------|--------------|-------------------|------------|
| Name of School Corporation: | | NOR | NORTH SPENCER COUNTY SCHOOL CO | | DL CO | Corp ID: | 747385 |
| Address of School Corporation: | | | 3720 E SR 162 | | | | |
| City: | Lincoln City | | Zip: | 47552 | | County Number: | 74 |
| VIN: | 4UZABRDU9BCAR786 | 62 | | License Number: | B713T | Bus Number: | 18 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2009 | Make of Chassis: | Freightliner | Year: | 2009 |
| Bus Type: | С | | | Mileage: | 120065 | | |
| Inspection Status | :: R | | Inspected By: | Philip Lubbers | | PE: | 7703 |

Violations - Rejected

| Inspection <u>Code</u> | Description |
|---------------------------|--|
| 41-1-8 | The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device. |
| 2-1-2 | Required number of back-up lights are not installed (2 required, additional 2 auxiliary allowed; 4 max) |
| 70-1-10 | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |
| 57-1-5 | Step-well light is missing or inoperative |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.