

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	12/13/2022	<b>Time:</b>	10:19 AM
<b>Name of School Corporation:</b>	BAUGO COMMUNITY SCHOOLS	<b>Corp ID:</b>	202260		
<b>Address of School Corporation:</b>	29125 CR 22 W				
<b>City:</b>	Elkhart	<b>Zip:</b>	46517	<b>County Number:</b>	20
<b>VIN:</b>	1BAKJCPA7BF278671	<b>License Number:</b>	860	<b>Bus Number:</b>	8
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2010	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	88084		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Joseph Hartman	<b>PE:</b>	7257

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
37-1-1	The horn does not operate at all
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
34-1-1	Any headlight is inoperative
64-1-4	Any front turn signal does not function properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus
7-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit
64-2-1	Any rear turn signal does not function properly

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**