

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------|------------------------|--------------|-------------------------|--------------|
| Type of Inspection: | Post-Crash Inspection | Date: | 8/25/2023 | Time: | 1:45 PM |
| Name of School Corporation: | PERU COMMUNITY SCHOOLS | Corp ID: | 525635 | | |
| Address of School Corporation: | 35 W 3rd St | | | | |
| City: | Peru | Zip: | 46970 | County Number: | 52 |
| VIN: | 4UZABRFC5RCUD2445 | License Number: | 25967 | Bus Number: | 4 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2022 | Make of Chassis: | Freightliner |
| Bus Type: | C | Mileage: | 18499 | | |
| Inspection Status: | O | Inspected By: | Randy McPike | PE: | 7018 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 24-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |
| 51-1-1 | Any door seals are missing, damaged, or torn |
| 70-1-7 | Any emergency window is too difficult to open |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 7-2-1 | There is no brake certification form the certification is expired or is not signed within the six-month requirement |
| 51-2-1 | The service door does not open or close properly |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.