

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/13/2023	Time:	10:56 AM
Name of School Corporation:	CROWN POINT COMM. SCHOOL CORP.			Corp ID:	454660
Address of School Corporation:	1151 E Summit				
City:	Crown Point	Zip:	46307	County Number:	45
VIN:	1T7Y84D22P1195444	License Number:	95294	Bus Number:	300
Make of Body:	Thomas Built Buses, Inc.	Year:	2022	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D			Mileage:	9031
Inspection Status:	O	Inspected By:	Tim Grayson	PE:	7558

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.